

Influenza Precautionary Measures Adopted by TurboJET

To prevent the spread of influenza, we have adopted a series of precautionary measures according to the advice from the Department of Health so as to provide a safe and comfortable journey for passengers. The precautionary measures are as follow:

1. Air Filter System

- 1.1 increase frequency of routine cleaning and sterilization of vessel air filter to a weekly basis;
- 1.2 increase vessel fresh air circulation when necessary;
- 1.3 install Biozone In-duct Air Purifier inside air duct of all vessels which can effectively kill airborne bacteria;

2. Cleaning and Sterilization Measures

- 2.1 use of disinfectant spray in vessel cabin every time after disembarkation and before embarkation;
- 2.2 clean and sterilize the sterilized carpet on exit/entrance of vessel on completion of every trip and thoroughly sterilize the carpet on completion of daily vessel operation;
- 2.3 use of automatic liquid soap machine at vessels' toilets;
- 2.4 clean and sterilize toilets, hand rails and door-handles during the journey and on completion of every trip;
- 2.5 clean and sterilize hand rails of gangway before embarkation and disembarkation;
- 2.6 clean and sterilize seat back trays and hand rests on completion of daily vessel operation;
- 2.7 clean and wipe with disinfectant provided onboard every vessel should cabin be contaminated with vomits or sputum;
- 2.8 wear mask and use of plastic gloves when undertaking cleaning duties and wash hands thoroughly on completion of cleaning duties;
- 2.9 equipped with a box containing masks, cotton balls, oral thermometer and thermometer sheaths;
- 2.10 use of disinfectant spray (ULV) in vessel cabin after daily vessel operation;
- 2.11 Clean and sterilize control panel in bridge after each shift of senior officers.

3. Cabin Services

- 3.1 substitute cotton hand towels with disposable wet tissue for onboard service;

4. Masks

- 4.1 provide masks to passengers upon request.

5. Waiting Hall (HK Macau Ferry Terminal)

- 5.1 frequently use of disinfectant spray in waiting hall;
- 5.2 provide disinfectant liquid for passenger use.

For information about influenza, please visit the website of Centre for Health Protection, Department of Health http://sc.info.gov.hk/gb/www.chp.gov.hk/view_content.asp?lang=en&info_id=2974